



15 Tarragon Place, Bradley Stoke
Bristol BS32 8TP
Telephone: 0117 979 1704
Fax: 0117 979 1979
E-mail: paul@weldinginspectionservices.com

WELDING INSPECTION SERVICES LTD

VISUAL INSPECTION REPORT

Ref. No. : WIS/F16
Issue 1

Welding Inspection Services Ref No : 2011 / 14687

GENERAL INFORMATION :

Client :	Vertical Extreme	Sheet No :	1 of 1
Location :	Bristol	Order No :	VE13042011
Inspector :	L Bibok	Date of Test :	13/04/2011
Qualification/Number :	PCN Level 2 & CSWIP / 208171		
Item Inspected :	One Off Climbing Wall		
Item Identification :	MW4-ANN		
Drawing Number :	Not Required		
Material and Dimension :	As Per Drawing		
Extent of Inspection :	100% Visual Of All Accessible Welds		
Stage of Test :	In Service Inspection		
Surface Conditions :	As Welded		

TECHNIQUE :

Inspection Procedure :	WIS/NDT/VIS/01 Issue 2A
Inspection Standard :	BS EN 970 : 1997
Viewing Conditions :	White Light 1000 Lux
Examining Equipment Used :	Inspection Kit One
Acceptance Standard :	BS EN ISO 5817 Level B (Stringent) : 1992

RESULTS :

A 100% Visual Inspection Was Carried Out By The Above Named Inspector. The Climbing Wall Was Acceptable To Specification .

ONE OF CLIMBING WALL M4W-ANN - ACCEPT

Name : Paul Robinson
PCN Level 2 & 3
Date : 18th April 2011

Signature :

